

El. vironmental Protection Agency 4500 S. Sixth Street Springfield, IL. 62706

Telephone 217-786-6892

June 30, 1981

Refer to: Sangamon Co./LPC -- #16782516

Springfield/Buerkett #2 (31st Street)

RECEIVED

JUN 30 1981

Mr. Merle Buerkett R. R. #2, Koke Mill Road Springfield, Illinois 62707

E.P.A. — D.L.P.C. STATE OF ILLINOIS

Dear Mr. Buerkett:

Your solid waste disposal facility located on the southeast side of Springfield was inspected on June 19, 1981, by David C. Jansen, representing this Agency.

The inspection disclosed the following conditions, which constitute violations of the Illinois Environmental Protection Act and Chapter 7 of the Illinois Pollution Control Board's Solid Waste Rules and Regulations:

... Previously deposited demolition waste consisting primarily of brick and wood had not received daily cover. This demolition waste is located on the east edge of Pit C and just south of the shredder building in Pit A.

... Daily cover was not being provided adequately in Pit C near the active area. All solid waste received daily must be covered with a minimum of six (6) inches of compacted suitable natural earthen material by the end of that day's operation.

... The completed portions of your site have not received an adequate depth of final cover. The areas found to be deficient are in Pits A and B.

EPA Region 5 Records Ctr. 298761 Mr. Merle Buerkett Page 2 June 30, 1981

> ... Leachate was seen seeping and ponded on the south edge of Pit B. Immediate action should be taken to correct this situation.

Your early compliance in this matter will be appreciated. In the event that you have any questions regarding compliance, please feel free to contact Mr. Jansen or me at the above number.

Sincerely,

more

Monte M. Nienkerk Central Region Manager Land Field Operations Section Division of Land/Noise Pollution Control

MMN/DCJ/cp

Enclosure

cc: VLPC/Division File
DLPC/FOS, Central Region
Sangamon Co. Health & Safety Commission

RECEIVED

JUN 30 1981

STATE OF ILLINOIS